



IECEx Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.:	NO/DNV/QAR09.0001/11	Page 1 of 1
QAR Free Ref. No.:	PRJC-598850-2019-PRC-NOR	Status: Issued
Details of change:	Re-Certification	Date of issue: 2025-05-20
Location(s) audited:	HMi Elements Limited Units A & B Windmill Industrial Estate Showfield Lane Malton YO17 6BT United Kingdom	Valid until: 2028-07-08 Audit date: 2025-04-07
Issuing ExCB:	PRE - DNV Product Assurance AS	
Manufacturer:	HMi Elements Limited Unit A & B, Windmill Industrial Estate Showfield Lane, Malton North Yorkshire YO17 6BT	
Location of Manufacturer:	United Kingdom	
Product information:	PCs, PC Terminals, HMI Equipment, WiFi access points, Media converter, Accessories	
Type of protection:	Ex d, e, m, i, n, t, op-is	
Related QARs:	NO/DNV/QAR09.0001/00NO/DNV/QAR09.0001/03NO/DNV/QAR09.0001/06NO/DNV/QAR09.0001/09 NO/DNV/QAR09.0001/01NO/DNV/QAR09.0001/04NO/DNV/QAR09.0001/07NO/DNV/QAR09.0001/10 NO/DNV/QAR09.0001/02NO/DNV/QAR09.0001/05NO/DNV/QAR09.0001/08	
Related Certificates (manual insertion)::		
Related Certificates (automatic linking)::		
Related Certificates for previous versions:	IECEx CML 15.0054X issue: 0IECEx CML 15.0054X issue: 3IECEx CML 15.0060U issue: 2IECEx CML 15.0097X issue: 1IECEx CML 15.0097X issue: 4IECEx CML 15.0097X issue: 7IECEx CML 19.0095X issue: 0IECEx CML 19.0095X issue: 3IECEx CML 19.0096X issue: 2IECEx CML 22.0093 issue: 0IECEx ITS 13.0017 issue: 1IECEx SIR 10.0061X issue: 1IECEx SIR 10.0061X issue: 4IECEx SIR 10.0061X issue: 7IECEx SIR 12.0109 issue: 1IECEx SIR 13.0128X issue: 0IECEx SIR 13.0128X issue: 3IECEx SIR 13.0128X issue: 6 IECEx CML 15.0054X issue: 1IECEx CML 15.0060U issue: 0IECEx CML 15.0060U issue: 3IECEx CML 15.0097X issue: 2IECEx CML 15.0097X issue: 5IECEx CML 15.0097X issue: 8IECEx CML 19.0095X issue: 1IECEx CML 19.0096X issue: 0IECEx CML 22.0092X issue: 0IECEx CML 24.0085X issue: 0IECEx ITS 13.0017 issue: 2IECEx SIR 10.0061X issue: 2IECEx SIR 10.0061X issue: 5IECEx SIR 10.0061X issue: 8IECEx SIR 12.0109 issue: 2IECEx SIR 13.0128X issue: 1IECEx SIR 13.0128X issue: 4IECEx SIR 13.0128X issue: 7 IECEx CML 15.0054X issue: 2IECEx CML 15.0060U issue: 1IECEx CML 15.0097X issue: 0IECEx CML 15.0097X issue: 3IECEx CML 15.0097X issue: 6IECEx CML 15.0097X issue: 9IECEx CML 19.0095X issue: 2IECEx CML 19.0096X issue: 1IECEx CML 22.0092X issue: 1IECEx ITS 13.0017 issue: 0IECEx SIR 10.0061X issue: 0IECEx SIR 10.0061X issue: 3IECEx SIR 10.0061X issue: 6IECEx SIR 12.0109 issue: 0IECEx SIR 13.0013U issue: 0IECEx SIR 13.0128X issue: 2IECEx SIR 13.0128X issue: 5	

Comments: